

FIG. 1




FIG. 2




FIG. 3




FIG. 4

FIG. 5




FIG. 6

210

SST

Scratch 0	...	Scratch 8
Start: 0 End: 0 Skew: 0 Thickness: T End pt: 347/1/177,144	...	Start: 8 End: 9 Skew: S Thickness: T End pt: 1,290/0/352,425
Scratch 9	Scratch 10	...
Start: 10 End: 13 Skew: S Thickness: T End pt: 2,368/0/242,298	Start: 12 End: 12 Skew: 0 Thickness: 0 End pt: 2,366/1/555,047	...

FIG. 7

216

PSI Table

	PSI	P - List
0	0	347/1/177,114
1	1	414/1/233,140
2	2	487/0/158,444
3	3	494/1/146,844
4	4	537/0/395,129
5	5	546/0/259,912
6	6	714/1/450,621
7	7	725/1/558,095
8	8	1,289/0/352,481
9	8	1,290/0/352,425
10	9	2,362/0/242,256
11	9	2,365/0/242,270
12	10	2,366/1/555,047
13	9	2,368/0/242,298

FIG. 8




FIG. 9

210

STT

...	Scratch 8	Scratch 9	...
...	Start: 8 End: 9 Skew: S Thickness: T End pt: 1,290/0/352,425	Start: 10 End: 11 Skew: 0 Thickness: T End pt: 2,365/0/242,270	...

	PSI	P - List
...
8	8	1,289/0/352,481
9	8	1,290/0/352,425
10	9	2,362/0/242,256
11	9	2,365/0/242,270
...

2,358/0/242,237	4
2,359/0/242,242	3
2,360/0/242,246	2
2,361/0/242,251	1
2,362/0/242,256	
2,363/0/242,260	1
2,364/0/242,265	2
2,365/0/242,270	
2,366/0/242,274	1
2,367/0/242,279	2
2,368/0/242,284	3
2,369/0/242,288	4

FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14